



SITE NAME:	TRW
SITE NUMBER:	0000070
ADDRESS:	513 Hendricks Street
CITY:	Shelbyville
COUNTY:	Shelby
SCORE:	42.83
SCORE DATE:	December 1990
CONTAMINANT TYPE:	Solvents
MEDIA AFFECTED:	Groundwater
CONTACT PERSON:	Ken Gill at (317) 233-0404
LAST REVISION:	December 2001
SITE PHOTO	
<p>STATUS: TRW operated two electronic connector manufacturing facilities in Shelbyville. One facility is located at 513 East Hendricks Street and the other is located 800 feet northeast on South Noble Street. Both facilities used tetrachloroethene and 1,1,1 trichloroethane as cleaning solvents. Due to poor housekeeping, these compounds were released into the soil and groundwater at both locations.</p> <p>TRW has performed remedial work on the soils that were effected and the company has installed a network of groundwater monitoring wells. The groundwater also is being pumped out and treated by an air stripper to clean it.</p> <p>IDEM has requested that TRW perform a complete and formal investigation using the historical data and collect any new data that may be needed. Part of this study would include a formal Risk Assessment. The study would address both the human impact and impact to the environment (especially the Big Blue River) from the contamination. A Feasibility Study would then be performed to determine the best remedial option for the site. In addition, a draft Human Health Risk Assessment is to be presented to IDEM by mid to late November 2000.</p>	